

TO BE FILLED BI THE INSPECTING OFFICER

1. Name of Officer : **AYISHABLI.K**
2. Name of School : Seva Sadan Central School, Pathiripala
3. Location/With Name of Education District/Sub District : Pathiripala
4. Classification of Building and size : 1. RCC Building(No.483)  
i. GF-970.18 Sqm  
ii. FF- 970.18 Sqm  
: 2. RCC Buildong(No.482)  
i. GF- 419.25 Sqm  
ii. FF- 208.12 Sqm
5. Period of Which the Certificate Issued : Provisional Fitness Certificate  
1.Asper High court order No.WP© No.15027/2019© dtd.31.05.2019  
2. Structural stability Certificate issued by Mohandas.KA, Associate Proffessor NSS Engineering College Palakkad dt.26.12.2018  
3. Challan No.KL001436243202021M dt.29.05.2020 Rs.1000/-  
4. Provisional fitness certificate from AEE, LSGD Ottapalam dtd.13.06.2019
6. Nature of defects any : No noticeable defects
7. Any major defects noticed which Will render the building unsafe in Any manner : No
8. Whether maintenance works have Been done properly : NA
9. Whether the structure is sound on On for conducting classes : Sound for cpnducting classes under normal weather & Wind Condition

Note: 1.The stability of the structure should be examined also with reference to Location, attitude. Intensity of wind exposure to flood etc.

2.Any additional observation is deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 22.06.2020 and found to be fit to conduct classes for the reason noted above for the period of 2020-21

Place : Lakkidi Perur GP

Date : 22.06.2020



*Ayisha*  
Assistant Engineer  
Local Self Govt. Dept.  
Lakkidi-Perur Grama Panchayath