

TO BE FILLED BY THE INSPECTING OFFICER

1. Name of Officer : **AYISHABLI.K**
2. Name of School : Seva Sadan Central School, Pathiripala
3. Location/With Name of Education District/Sub District : Pathiripala
4. Classification of Building and size : 1. RCC Building(No.483)
i. GF-970.18 Sqm
ii. FF- 970.18 Sqm
: 2. RCC Building(No.482)
i. GF- 419.25 Sqm
ii. FF- 208.12 Sqm
5. Period of Which the Certificate Issued : **Provisional Fitness Certificate (2021-22)**
6. Nature of defects any : No noticeable defects
7. Any major defects noticed which Will render the building unsafe in Any manner : No
8. Whether maintenance works have Been done properly : NA
9. Whether the structure is sound on On for conducting classes : Sound for conducting classes under normal weather & Wind Condition


Note: 1.The stability of the structure should be examined also with reference to Location, attitude, Intensity of wind exposure to flood etc.

2.Any additional observation is deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 31/05/2021 and found to be fit to conduct classes for the reason noted above for the period of 2020-21

Place : Lakkidi Perur GP

Date : 31/05/2021



Ayisha
Assistant Engineer
Local Self Govt. Dept.
Lakkidi-Perur Grama Panchayath